

ANEXO I

Cuadro 5: Bienes asociados de la quebrada Aeropuerto, margen derecha.
(Coordenadas en UTM WGS-84, Zona 19 S)

Limite Superior de la Faja Marginal - LSFM						Limite Superior de la Ribera - LSR	
Vértice	Código	Progresiva	Este	Norte	Ancho	Este	Norte
1	-	-	476364.21	8607449.66	3.00	476362.77	8607452.30
2	HMD-001	0+023	476347.60	8607437.13	3.00	476345.15	8607438.91
3	-	-	476342.89	8607421.44	3.00	476339.89	8607421.71
4	HMD-002	0+070	476339.22	8607388.86	3.00	476337.84	8607398.37
5	-	-	476286.29	8607319.29	5.00	476289.08	8607325.28
6	HMD-003	0+194	476256.04	8607313.05	5.00	476255.27	8607315.95
7	-	-	476221.17	8607294.20	5.00	476219.94	8607296.94
8	-	-	476178.57	8607272.40	5.00	476175.28	8607276.27
9	HMD-004	0+330	476138.95	8607247.34	5.00	476136.66	8607251.79
10	-	-	476106.11	8607231.42	5.00	476103.53	8607235.73
11	-	-	476079.23	8607207.13	5.00	476076.60	8607211.39
12	HMD-005	0+444	476041.97	8607188.99	5.00	476040.11	8607193.64
13	-	-	475992.52	8607173.44	5.00	475991.28	8607178.29
14	-	-	475960.55	8607155.88	5.00	475959.16	8607160.71
15	HMD-006	0+560	475926.26	8607151.80	5.00	475926.82	8607156.82
16	-	-	475898.83	8607171.46	5.00	475901.55	8607175.76
17	-	-	475880.95	8607186.71	5.00	475883.12	8607191.22
18	-	-	475850.52	8607213.24	5.00	475854.51	8607216.25
19	-	-	475821.55	8607250.67	5.00	475825.94	8607253.06
20	HMD-007	0+725	475811.45	8607274.50	5.00	475816.41	8607275.30
21	-	-	475812.12	8607294.84	5.00	475817.10	8607294.42

Cuadro 6: Bienes asociados de la quebrada Aeropuerto, margen izquierda.
(Coordenadas en UTM WGS-84, Zona 19 S)

Limite Superior de la Faja Marginal - LSFM						Limite Superior de la Ribera - LSR	
Vértice	Código	Progresiva	Este	Norte	Ancho	Este	Norte
1	-	-	476360.27	8607456.63	3.00	476361.79	8607454.04
2	HMI-001	0+012	476349.27	8607450.19	3.00	476351.13	8607447.80
3	-	-	476336.87	8607433.71	3.00	476339.75	8607432.76
4	-	-	476334.73	8607403.63	3.00	476337.72	8607402.97
5	HMI-002	0+077	476327.76	8607388.86	3.00	476328.70	8607383.86
6	-	-	476282.89	8607334.84	5.00	476283.01	8607327.67
7	HMI-003	0+190	476254.87	8607331.36	5.00	476256.02	8607326.49
8	-	-	476223.96	8607315.45	5.00	476226.24	8607310.99
9	-	-	476199.99	8607306.59	5.00	476201.34	8607301.77
10	HMI-004	0+300	476155.99	8607278.76	5.00	476158.75	8607274.59
11	-	-	476129.80	8607265.14	5.00	476132.09	8607260.69
12	-	-	476095.82	8607248.66	5.00	476098.39	8607244.35
13	HMI-005	0+437	476040.95	8607210.36	5.00	476043.07	8607205.83
14	-	-	475980.35	8607190.48	5.00	475982.63	8607185.97
15	-	-	475940.18	8607172.27	5.00	475940.74	8607167.28
16	-	-	475920.88	8607183.89	5.00	475918.09	8607179.65
17	HMI-006	0+594	475909.70	8607188.64	5.00	475906.98	8607184.35
18	-	-	475881.19	8607209.71	5.00	475878.18	8607205.72
19	-	-	475856.63	8607234.46	5.00	475852.43	8607231.43
20	HMI-007	0+710	475835.83	8607266.42	5.00	475831.38	8607264.13
21	-	-	475832.05	8607293.14	5.00	475827.07	8607293.57